Approved For Release 2001/05/04: CIA-RDP62B00844R000200090077-0

CHAL-0156 Copy 6 of 6

26 May 1958

MEMORANDUM FOR: Development Officer, DPS/DCI

THR OUGH

: Director of Development & Procurement, DPS/DCI

SUBJECT

: B Camera Reliability

25X1A

25X1A REFERENCES

: A. CHAL-0073, dated 20 May 1958

1397 (IN 39897) dated 22 May 1958

 I have noted with interest the report on camera reliability in Reference A and especially the comments in paragraph 5 on B camera performance. I believe you are already aware of my conversations on this matter with and others during my visit to Detachment B some weeks ago.

- 2. Reference B is the report from Detachment B that was promised me when I left there. I have considerable confidence in the competence of the Hycon personnel now at Detachment B and have every reason to believe that their diagnosis of the cause of trouble is accurate. Moreover, their recommendation in paragraph 2.c. of Reference B, that a careful record be kept on all critical parts, impresses me as an eminently sensible one that will involve considerable record-keeping but cannot fail to enhance reliability.
- 3. I note that Reference B was sent to our Headquarters without even an information copy to Hycon. In this connection, you should be aware 25X1A that specifically requested me to refrain from advising Hycon of their efforts to diagnose the cause of shutter failure until they had arrived at some conclusions and could submit a report such as that contained in Reference B. Their reason was their fear that the company would disapprove of an essentially R & D type of operation in the field. In deference to their request, I have had no discussion with Hycon personnel since my return,

Approved For Release 2001/05/04: CIA-RDP62B00844R000200090077-0

SECRET

CHAL-0156 Page Two

- 4. Against the foregoing background, I believe the following steps are now in order:
 - a. First, I believe we should send the message along the general lines of the draft attached hereto to Detachment B. The draft is self-explanatory.
 - b. Unless the Detachment has made or prefers to make its own report direct to Hycon, the substance of Reference B should be passed along to Hycon with a request for their views.
 - c. Unless their reaction is negative, steps should be taken at once to comply with the recommendations in paragraphs 2.b. and 2.c. of Reference B -- i.e., the trip latch mechanism should be made a FAK item and spares supplied to the field and service records to components should be instituted.
 - d. Simultaneous with the action in 4.c. (above), Detachment C should be advised of the substance of Reference B.
- 5. If you concur, would you carry out the foregoing. If not, I would appreciate your comments.

SIGNED

RICHARD M. BISSELL, JR. Special Assistant to the Director for Planning and Development

Attachment:

Draft Cable

RMB:ggs (24 May 1958)

Distribution:

- Copy 1 Development Offr. DPS
 - 2 Dir of D&P, DPS
 - 3 Dir of Ops, DPS
 - 4 Deputy Director, DPS
 - 5 SA/PD/DCI Subj (FU)
 - 6 SA/PD/DCI CHAL Chrono